


# Quittapahilla Creek Watershed Assessment Volume 1 – Findings Report



December 2006



**CLEAR CREEKS CONSULTING**

1317 Knopp Road, Jarrettsville, Maryland 21084

(410) 692-2164



# **Quittapahilla Creek Watershed Assessment Volume 1 – Findings Report**

**Prepared For**

**Quittapahilla Creek Watershed Association**

**Prepared By**

**Clear Creeks Consulting LLC  
Jarrettsville, MD**

**In Association with**

**Skelly & Loy, Inc.  
Harrisburg, PA**

**December 2006**

## TABLE OF CONTENTS

### Executive Summary

#### Section 1 – Introduction

1.1	Introduction	1
1.2	Project Study Area and Background	1
1.3	Project Goals and Objectives	4
1.4	Project Study Components	4
1.4.1	Watershed Characterization	4
1.4.2	Morphological Stream Assessment	9
1.4.3	Subwatershed Analysis	11
1.4.4	Ecological Assessment	12
1.4.5	Water Quality Assessment	13

#### Section 2 – Watershed Characterization

2.1	Introduction	17
2.2	Physiography	17
2.3	Climate	18
2.4	Basin Morphometry	19
2.5	Geology and Soils	19
2.6	Land Use and Land Cover	20
2.7	Hydrology	32
2.7.1	U.S. Geological Survey Stream Gage Record Analysis	32
2.7.2	Field Calibration of Bankfull Discharge	32
2.7.3	U.S. Geological Survey Regional Regressions	33
2.7.4	100 Year Floodplains	33
2.7.5	Hydrologic Modeling and Analysis	34

#### Section 3 – Morphologic Stream Assessment

3.1	Introduction	40
3.2	Field Calibration Surveys to Verify Bankfull Channel Field Indicators	40
3.3	U.S. Geological Survey Regional Regressions	40
3.4	Geomorphic Features of Quittapahilla Creek	41
3.5	Morphological Description and Assessment of Stream Condition	42
3.6	Level IV Stream Stability Validation Monitoring	46
3.7	Findings of Channel Morphology and Stability Assessment	47
3.7.1	General Overview of Stream Conditions	47
3.7.2	Detailed Descriptions of Main Stem Segments	47

## Section 4 – Subwatershed Analyses

4.1	Introduction	209
4.2	Field Reconnaissance Findings	209
4.2.1	General Comments	209
4.2.2	Agriculture	209
4.2.3	Stream Bank Fencing Program	213
4.2.4	Other Streamside Agricultural Best Mgmt. Practices	217
4.2.5	Logging and Lumber Mills	219
4.2.6	Quarries	221
4.2.7	Development	226
4.2.8	Channel Alterations	233
4.2.9	Flow Diversions	242
4.2.10	Fish Barriers	246
4.2.11	Fish Habitat Structures	247

## Section 5 – Ecological Assessment

5.1	Introduction	249
5.2	Historical Biological Communities	249
5.3	Trout Stocking in the Quittapahilla Creek Watershed	250
5.4	Evaluation of Existing In-Stream Habitat	250
5.4.1	Rationale	250
5.4.2	Detailed Description of Main Stem Segments	252
5.5	Existing Biological Communities	259
5.5.1	Methodology	259
5.5.2	Benthic Macroinvertebrate Communities	261
5.5.3	Fish Communities	269
5.5.4	Station by Station Summary of Existing Biological Communities	271
5.5.5	Ecological Assessment Summary	283

## Section 6 – Water Quality Assessment

6.1	Introduction	286
6.2	Historic Water Quality Conditions	286
6.3	Total Maximum Daily Loads (TMDL) Study	287
6.4	Water Quality Modeling and Analysis	288
6.4.1	General Overview Rationale and Methodology	288
6.4.2	Refinements to Modeling Approach	289
6.4.3	Substitution of More Detailed Data	289
6.4.4	Model Calibration	292
6.4.5	Model Application and Results	294
6.5	Point Source Discharges	306
6.6	Existing Water Quality Conditions	308